

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Vehicle Information



Year:2014

Make:AUSTHOLDEN

Model:Commodore

VIN:6G1EK5E54CL722314

Vehicle Software Version:V44.20

Diagnostic Application Version:V8.00.037

Diagnostic path:Manually Select > (E) 2014 > Commodore > Health Report

Repair Shop

Shop Name:

Address:

Zip Code:

Telephone:

Email:

SN:987940058893

Test Time:2026-05-15 20:37:45



System fault code 【Pre-Repair】

The following systems is abnormal:

Engine Control Module (ECM)

DTC (2)

1.P0171-00 Fuel Trim System Lean

Passed And Failed

2.P0174-00 Fuel Trim System Lean Bank 2

Passed And Failed

Instrument Cluster (IC)

DTC (2)

1.U0159-00 Lost Communication With Parking Assist Control Module

Passed And Failed

2.U0168-00 Lost Communication With Keyless Entry Control Module

Passed And Failed

Radio (RADIO)

DTC (1)

1.B125A-04 Antenna Signal Circuit - Open

History

Heating Ventilation And Air Conditioning Control Module (HVACCM)

DTC (2)

1.B0253-61 Blend Face and Floor Air Flow Control Circuit - Stuck

History

2.B0418-61 Right Temperature Control Circuit - Stuck

History

The following systems are OK:

1.Chassis Control Module (CCM)

2.Transmission Control Module (TCM)

3.Electronic Brake Control Module (EBCM)

4.Body Control Module (BCM)

5.Inflatable Restraint Sensing And Diagnostic Module (IRSDM)

6.Keyless Entry Control Module (KECM)

7.Parking Assist Control Module (PACM)



Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!